		Sir y Fflint				ADDRESS	NUMBER OF UNITS	ARCHETYPE	ADDRESS	NUMBER OF UNITS	ARCHETYPE	ADDRESS	NUMBER OF UNITS	ARCHETYPE
	SHELTER REVIEW MATRIX - HOUSING & ESTATES	Flintshire		RATIONALE		Block 1	41		Block 2	33		Block 3	62	
REF	MATRIX CATEGORIES	CRITERIA / CONSIDERATIONS	HIGH	MEDIUM	LOW	SCORE	ACTUAL DATA	COMMENTS	SCORE	ACTUAL DATA	COMMENTS	SCORE	ACTUAL DATA	COMMENTS
1	DESIREABILITY		10-8	7-4	3-0									
								Good reputation, accessible flats can be sought after			Good reputation, accessible flats can be sought after.			Good reputation
b	Recutational issues  ASB Incidents	NHO NPUT  REACT CASEN/POLICE STATS	Police & Ten. Enforcement Involved  Police Involved, High number, Any cases on React	Housing Officer & other tenants aware  Medium Number, Any cases on React	Only tenants/ local residents  Low number			Currently only ASB reported is youths gathering outside	4		Currently one case on React re noise nuisance. Also have just mediated a dispute over children from a house annoying tenants which didn't get as far as React. Generally a quiet scheme.		0	N/A
	Car Parkina	SASS OF CAS PARKING AND AVAILABILITY	Less than 50% weilable = 10 Score	between 50% - 80% available = 5 Score	Over 80% available = 0 Score			Parking is poor - on outskirts of scheme so even to access some GF flists can mean a walk that excludes many disabled applicants. Small number of five spaces close by, with only one disabled sease, other careark accessible by stress at fix end			Parking is very poor. There is just one carpain to the rear of the flats which is usually full. It is also on a substantial slope and has a steep path down to the flats, which runs under trees and can be slippery in auturn/winter.			Parking requires review
	Amerities	ESSENTIAL AMENITIES WITHIN IMMEDIATE CATCHMENT AREA	No shoos, pharmacies, bus routes in close prox.	Limited amenities in close prox.	Sufficient amenities in close prox.			Excellent access to town centre			Excellent access to town centre.		,	Excellent access to town centre.
		PROXIMETY TO PUBLIC TRANSPORT	Unavailable, exceeds 0.1 mile	Close proximity. Low Frequency	Close proximity, High Frequency			Directly outside where buses go from. May have to so down steas depending on route.			The flats have excellent access to bus services. However depending on where the individual flat is located, access can involve a medium walk involving hills and steps.		2	Very good access to all services
f	Limited Social networks etc.	ASO INPUT	No Availability	Limited Availability	High Availability/ Access with varied options		3	Scheme has a communal room, right by town centre	1		Scheme has communal room and provided people can do the hill, the scheme is right by the town centre.		2	Very good access to all services
	Location and Accessibility Existing Tenant Satisfaction Survey	REMOTE COMPLEX, SITUATED ON A HEL WITH MUTURE STEPS TO ACCESS PROPERTY ETC SATISFACTION SURVEY RESULTS WITH MEMORS TO PROPERTY/COMPLEX ETC.	Remote, Located on a steep hill with Multiple Steps etc.  Below 60% Sainsfaction Score = 10	Remote and Difficult to Access  Bollow 80% above 60% Score = 5	Close to Town Centre, Good Access for all users Above 80% Score = 0			May need to ascend steps. Right next to Town Centre but most direct route does involve walking down quite a steep incline. See car parking issues above.	é		Short walk from town centre - very close but depending on where flat is can mean a walk up a steep hill or stairs.		2	Short walk from Lown centre
	Local Member Approval for Scheme re-designation	LOCAL MEMBER SUPPORT	Local Member in Favour = 10 Score		Local Member against reclassification = 0 Score									
2	ATTRIBUTES	LOCAL NEWBER SUPPORT	Local Memoer in Payour = 10 Score		Local Nember against reclassification = 0 Score									
	Access / Elevator Lifts etc.	ACCESS	Access via Stees/Stairs only - Very difficult to access	Access via Steos /Stairs only - Difficult to access	Lifts. Stair Lifts. No Steps - Easy Access		6	First and second floor flats are upstains, no lifts. Even ground floor flats may be a distance from parking - no guaranteed parking spaces. Hill to town centre	s	s.	Second and first floor flats are upstairs, no lift. Many "ground floor" flats are accessed only by long walts and stens or steno catch. Access side flats very steeo.		2	Very rood
ь	Scooter Storage Security	EASE OF SCOOTER STORAGE AND AVAILABILTY  KMS COMMUNAL ACCESS CONTROL. CAMERAS. LIGHTING	Less than 50% available = 10 Score  Security Low - No Security Equipment etc.	Between 50% - 80% available = 5 Score Security Medium - RMS Installed	Over 80% available = 0  KMS Installed. Cameras and Excellent Lighting	1		No specific storage or charging.  No security equipment	10		No specific storage or charging  No security equipment		10	No specific storage or charging  No security equipment
d	Allocated Communal Garden' Outdoor Space LOW AVAILABILITY OF SHELTERED STOCK IN AREA	GAIDERS OR OUTDOOR SPACE TO SOCIALISE	Sacurity Low - No Sacurity Couldment etc.  No Availability	Security Analysis - AMS incased  Limited Analysisty	Mich Ausliability/ Access with varied ootions			Good communal garden areas maintained by Council. Tenants have own benches, flower pots etc. without the resoonsibility of a full earden.			Good communal garden areas maintained by Council. Tenants have com benches, flower pots etc. without the responsibility of a full earden.		0	Good communal garden areas maintained by Council. Tenants have own benches, flower pots etc. without the responsibility of a full earden.
	Alternative stock TURNOVER Average lendth of tenancy	ALTERNATING SHE STREED STOCK WITHIN CLOSE PROMARTLY HOW LONG ON AVERAGE STREAMS	High Availability / Access with varied options Less than 2 years = 10 Score	Limited Availability  Over 2 wears but under 5 years = 5 Score	No Availability Over 5 vess = 0 Score			More Flats across the road, but has worse access issues as built into top of steep NII. More flats jost off High Street and half of these are ground floor but parking very limited and poor reputation.	5		Across road from More Flats which has slightly better access as the hill is less pronounced. More flats just off high street but poor parking and reputation, plus half are first floor.		5	No other accommodation nearby
ь	Number of Terminations	HOW LONG ON AVERAGE TENANTS REMAIN	More than 10% = 10 Score	Less than 10% but more than 5% = 5 Score	Less than 5% = 0 Score		0 5				0		0	0
¢	Waitino list/demand	WAITING LIST VOLUME	Less than 10% - 10 Score	Less than 10% but more than 5% = 5 Score	More than 10% = 0 Score	1		Currently 7 people on list who all need ground floor, wet room and level access approach. Few flats meet this criberia.	26	i ·	Currently 2 people on list who all need ground floor, wet 7 room and level access accroach. Few flats meet this criteria.		0 :	15 15 on waitine list. highly sought after

SCORES 72 76 38